

VENTILATION AUDIT REPORT Version 2

SCHOOL:	Cargo Public School (1506)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Orange
LOCAL GOVERNMENT AREA:	Cabonne

1506 - Cargo Public School
Site Plan (12220)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Reading Area - (34.63 SQM)	 Student Space (16)	
B00A - R0002 - Special Programs Room - (10.77 SQM)	 Student Space (4)	
B00A - R0003 - Home Base - (50.96 SQM) - Teaching Space: 1	 Student Space (28)	
B00B - R0001 - Withdrawal Space - 1hb - (12.7 SQM)	 Student Space (5)	
B00B - R0002 - Home Base - (39.91 SQM) - Teaching Space: 1	 Student Space (22)	
B00E - R0001 - Movement - (8.56 SQM)	Not Applicable	Circulation or storage space.
B00E - R0002 - Clerical Office - (10.67 SQM)	 Office (2)	
B00E - R0004 - Principal - (13.75 SQM)	 Office (3)	
B00E - R0005 - Staff Room - (26.08 SQM)	 Office (6)	
B00E - R0008 - Entry Vestibule - (8.09 SQM)	Not Applicable	Circulation or storage space.
B00H - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	