


SCHOOL:	Coolongolook Public School (1627)
AMU REGION:	North Coast
STATE ELECTORATE:	Myall Lakes
LOCAL GOVERNMENT AREA:	Mid-Coast



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (13.23 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Principal - (15.05 SQM)	Office (3)	
B00A - R0003 - Interview - (13.39 SQM)	Office (3)	
B00A - R0004 - Staff Room - (17.9 SQM)	Office (4)	
B00A - R0010 - Entry Vestibule - (18.64 SQM)	Not Applicable	Circulation or storage space.
B00A - R0011 - Clerical Office - (9.84 SQM)	Office (2)	
B00A - R0013 - Duplicating Workroom - (15.78 SQM)	Office (3)	
B00A - R0014 - Staff Room Annexe - (15.05 SQM)	Office (3)	
B00F - R0001 - Seminar/Study - (16.74 SQM)	Office (4)	
B00F - R0003 - Home Base - (46.74 SQM) - Teaching Space: 1	Student Space (47)	
B00F - R0005 - Home Base - (46.74 SQM) - Teaching Space: 1	Student Space (47)	
B00F - R0006 - Canteen - (12.89 SQM)	Not Applicable	Circulation or storage space.
B00F - R0009 - Withdrawal Space - 1hb - (8.28 SQM)	Student Space (3)	
B00G - R0001 - Practical Activity Area - (20.15 SQM)	Student Space (9)	
B00G - R0002 - Practical Activity Area - (24.16 SQM)	Student Space (11)	
B00I - R0001 - Reading Area - (59.86 SQM)	Student Space (27)	