

VENTILATION AUDIT REPORT Version 2

SCHOOL:	Kingstown Public School (2310)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Uralla

2310 - Kingstown Public School
Site Plan (10636)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Reading Area - (48.33 SQM)	 Student Space (22)	
B00A - R0004 - Clerical Office - (10.88 SQM)	 Office (2)	
B00A - R0005 - Principal - (7.07 SQM)	 Office (1)	
B00B - R0001 - Movement - (21.03 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Staff Room - (20.7 SQM)	 Office (5)	
B00C - R0004 - Home Base - (67.77 SQM) - Teaching Space: 1	 Student Space (61)	
B00C - R0006 - Home Base - (49.92 SQM) - Teaching Space: 1	 Student Space (38)	
B00F - R0001 - Home Base - (59.97 SQM) - Teaching Space: 1	 Student Space (35)	
B00H - R0002 - Staff Kitchen - (5.82 SQM)	 Office (1)	
B00H - R0003 - Special Programs Room - (31.25 SQM)	 Student Space (14)	