


VENTILATION AUDIT REPORT Version 2

SCHOOL:	Nymboida Public School (2784)
AMU REGION:	North Coast
STATE ELECTORATE:	Clarence
LOCAL GOVERNMENT AREA:	Clarence Valley

2784 - Nymboida Public School
Site Plan (10714)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (26.95 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Staff Kitchen - (11.38 SQM)	 Office (2)	
B00A - R0006 - Clerical Office - (23 SQM)	 Office (5)	
B00A - R0007 - Sick Bay - (5 SQM)	 Student Space (2)	
B00A - R0008 - Movement - (6 SQM)	Not Applicable	Circulation or storage space.
B00A - R0009 - Principal - (10 SQM)	 Office (2)	
B00A - R0011 - Staff Room - (24 SQM)	 Office (6)	
B00B - R0001 - Movement - (6.12 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Movement - (60.51 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Canteen - (12.32 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	 Student Space (33)	