


VENTILATION AUDIT REPORT Version 2

SCHOOL:	Wallendbeen Public School (3353)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Cootamundra-Gundagai

3353 - Wallendbeen Public School
Site Plan (12017)



1:808

Printed: 21-Mar-2020

Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (47.13 SQM) - Teaching Space: 1	 Student Space (25)	
B00A - R0003 - Staff Kitchen - (6.06 SQM)	 Office (1)	
B00A - R0006 - Clerical Office - (10.03 SQM)	 Office (2)	
B00A - R0007 - Staff Room Annexe - (22.73 SQM)	 Office (5)	
B00A - R0008 - Staff Kitchen - (20.86 SQM)	 Office (5)	
B00B - R0002 - Reading Area - (10.47 SQM)	 Student Space (4)	
B00C - R0001 - Movement - (20.94 SQM)	Not Applicable	Circulation or storage space.
B00F - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	