


# VENTILATION AUDIT REPORT Version 2

<b>SCHOOL:</b>	<b>Wattle Flat Public School (3402)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Bathurst</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Bathurst</b>

3402 - Wattle Flat Public School  
Site Plan (12896)



Site plan is indicative only and is included to show building numbers used by the Department.

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Communal Space - (88.22 SQM)	● Student Space (40)	
B00A - R0003 - Staff Room - (25.73 SQM)	● Office (6)	
B00A - R0004 - Practical Activities - 1hb - (18.54 SQM)	● Student Space (8)	
B00B - R0001 - Clerical Office - (15.73 SQM)	● Office (3)	
B00B - R0002 - Reading Area - (46.66 SQM)	● Student Space (21)	
B00B - R0003 - Movement - (6.43 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	● Student Space (70)	
OS 603 12267 - OS 603 12267 - Learning Unit - Standard With P.A.A. A/C - (76 SQM)	● Student Space (35)	